



NOTE #3: Service replacement of the ONE (1) piece driveshaft is not being offered. The following Gear Housing Assemblies are "GENERIC". They DO NOT INCLUDE THE UPPER DRIVESHAFT (REF. #43) on gear housing breakdown pages. You MUST ALSO ORDER the respective driveshaft extension kit listed below. Before ordering, determine the length of the driveshaft and the number of splines on the driveshaft.

GEAR HOUSING CHART (S/N-0G438000 & UP)



