



2958

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	896702	1		
2		1	· TURBINE HOUSING	
3		1	· NOZZLE RING	
4		1	· BEARING HOUSING	
5		2	· BUSHING	IK
6		2	· THRUST WASHER	IK
7	417727	3	· Lock ring	IK
8		1	· ROTOR	
9		1	· · SHAFT WITH TURBINE WHEEL	
10		1	· · THRUST COLLAR	
11		1	· · COMPRESSOR WHEEL	
12		1	· · NUT	
13	335538	2	· Piston ring	IK
14	417731	2	· Piston ring	IK
15	417733	X		IK TH = 0,002"
	417734	X		IK TH = 0,005"
	417735	X		IK TH = 0,010"
16		1	· THRUST BEARING	IK
17		1	· SPRING	
18		1	· HOUSING	
19	417736	1	· Gasket	IK
20		4	· SCREW	
21	417748	4		IK
22	417749	4		IK
23		1	· PLATE	
24	422360	1	· Lock ring	IK
25		1	· PLATE	
26	411810	8	· Screw	
27	417741	4	· Lock plate	IK
28		1	· COMPRESSOR INLET	
29	417525	1	· O-ring	IK
30		1	· HOUSING	
31	338587	1	· Gasket	IK
32		1	· LOCK RING	
33	411811	8	· Screw	
34	417745	4	· Lock plate	IK
35		1	· EMBLEM	
36	955117	3		
37	417382	1	· Gasket	IK
38	417378	1	· Gasket	IK
39	417381	1	· Gasket	IK
	276280	1	Repair kit	